

2010 Monitoring Summary



Mill Creek at Cherokee County Road 2 (33.97058/-85.60120)

BACKGROUND

The Alabama Department of Environmental Management (ADEM) selected the Mill Creek watershed for biological and water quality monitoring as part of the 2010 Alabama, Coosa, Tallapoosa (ACT) Basin Assessment. The objectives of the project were to assess the biological integrity of each monitoring site and to estimate overall water quality within the basin.



Figure 1. Downstream view of Mill Creek at MLLC-4, September 9, 2010.

WATERSHED CHARACTERISTICS

Watershed characteristics are summarized in Table 1. Mill Creek is a Fish & Wildlife (F&W) stream located a few miles north of the city of Piedmont in the Southern Limestone/Dolomite Valleys and Low Rolling Hills ecoregion (67f). Based on the 2006 National Land Cover Dataset, landuse within the watershed is predominantly forest (62%) with some pastures and urban development (14%). As of September 1, 2012, ADEM's NPDES Management System database shows a total of 13 permitted discharges within the watershed.

REACH CHARACTERISTICS

General observations (Table 2) and a habitat assessment (Table 3) were completed during the macroinvertebrate assessment. In comparison with reference reaches in the same ecoregion, they give an indication of the physical condition of the site and the quality and availability of habitat. Mill Creek at MLLC-4 is a high-gradient, riffle-run stream with substrate composed primarily of bedrock (Figure 1). Overall habitat quality and availability was rated as sub-optimal. The reach was characterized by limited riparian buffers and unstable banks.

BIOASSESSMENT RESULTS

Benthic macroinvertebrate communities were sampled using ADEM's Intensive Multi-habitat Bioassessment methodology (WMB-I). The WMB-I uses measures of taxonomic richness, community composition, and community tolerance to assess the overall health of the macroinvertebrate community. Each metric is scored on a 100 point scale in comparison to leastimpaired reference reaches in the same ecoregion. The final score is the average of all individual metric scores. Metric results indicated the macroinvertebrate community to be in *fair* condition (Table 4).

Table 1. Summary of watershed characteristics.

Basin		Coosa River
Drainage Area (mi²) Ecoregion ^a		23
		67f
% Landuse		
Open water		<1
Wetland	Woody	<1
Forest	Deciduous	21
	Evergreen	30
	Mixed	11
Shrub/scrub	3	
Grassland/herbaceous		2
Pasture/hay		16
Cultivated crops		3
Development	Open space	8
	Low intensity	5
M	oderate intensity	1
	High intensity	<1
Barren		<1
Population/km ^{2b}		118
# NPDES Permits ^c	TOTAL	13
Construction Storm	9	
Industrial General	1	
Underground Inject	3	

- Southern Limestone/Dolomite Valleys and Low Rolling Hills
- b. 2000 US Census
- c. #NPDES permits downloaded from ADEM's NPDES Management System database, September 1, 2012

Table 2. Physical characteristics of Mill Creek at MLLC-4, May 27, 2010.

Physical Characteristics					
Width (ft)		30			
Canopy Cover		Estimate 50/50			
Depth (ft)					
	Riffle	0.5			
	Run	1.5			
	Pool	2.5			
% of Reach					
	Riffle	5			
	Run	85			
	Pool	10			
% Substrate					
	Bedrock	80			
	Boulder	1			
	Cobble	3			
	Gravel	3			
	Sand	3			
	Silt	3			
	Organic Matter	7			

Table 3. Results of the habitat assessment conducted on Mill Creek at MLLC-4, May 27, 2010.

Habitat Assessment	%Maximum Score	Rating
Instream Habitat Quality	y 73	Optimal >70
Sediment Deposition	n 88	Optimal >70
Sinuosit	y 90	Optimal >84
Bank and Vegetative Stability	y 51	Marginal (35-59)
Riparian Buffe	r 48	Poor < 50
Habitat Assessment Score	167	
% Maximum Score	70	Sub-optimal (59-70)

Table 4. Results of the macroinvertebrate bioassessment conducted in Mill Creek at MLLC-4, May 27, 2010.

Macroinvertebrate Assessment						
	Results	Scores				
Taxa richness and diversity measures		(0-100)				
# EPT taxa	22	78				
Shannon Diversity	3.76	49				
Taxonomic composition measures						
% EPT minus Baetidae and Hydropsychidae	44	47				
% Non-insect taxa	21	11				
Tolerance measures						
% Tolerant taxa	27	62				
WMB-I Assessment Score		50				
WMB-I Assessment Rating		Fair (47-69)				

WATER CHEMISTRY

Results of water chemistry analyses are presented in Table 5. In situ measurements and water samples were collected bimonthly May through November of 2010 to help identify any stressors to the biological communities.

Organics were collected at MLLC-4 on May 5th and September 9th, but all parameters were below detection limits. Median concentrations of nitrate+nitrite nitrogen and dissolved manganese were higher than expected for ecoregion 67f. Median specific conductance and hardness were higher than background levels for ecoregion 67f. Copper exceeded aquatic life use criteria on one of four occasions.

SUMMARY

Bioassessment results indicated the macroinvertebrate community to be in *fair* condition. Overall habitat quality was categorized as *sub-optimal* due to a poor riparian buffer and unstable banks. Conductivity, hardness, nitrate+nitrite nitrogen, copper, and dissolved manganese were higher than expected for ecoregion 67f. Monitoring should continue to ensure that water quality and biological conditions remain stable.

FOR MONITORING INFORMATION, CONTACT: Alicia K. Phillips ADEM Environmental Indicators Section 1350 Coliseum Boulevard Montgomery, AL 36110 (334) 260-2797 akphillips@adem.state.al.us

Table 5. Summary of water quality data collected May-November, 2010. Minimum (Min) and maximum (Max) values calculated using minimum detection limits (MDL). Median, average (Avg), and standard deviations (SD) values were calculated by multiplying the MDL by 0.5 when results were less than this value.

Parameter	N		Min		Max	Med	Avg	SD	E
Physical									
Temperature (°C)	5		12.2		23.4	20.0	19.5	4.5	
Turbidity (NTU)	5		1.8		17.2	8.9	9.7	5.8	
Total Dissolved Solids (mg/L)	4		100.0		132.0	117.0	116.5	14.3	
Total Suspended Solids (mg/L)	4		3.0		5.0	3.5	3.8	1.0	
Specific Conductance (µmhos)	5		149.3		249.6	233.2 ^G	222.1	41.4	
Hardness (mg/L)	4		66.1		118.0	114.0 ^G	103.0	24.7	
Alkalinity (mg/L)	4		69.5		126.0	121.0	109.4	26.7	
Stream Flow (cfs)	5		2.7		31.1	7.0	10.2	11.9	
Chemical									
Dissolved Oxygen (mg/L)	5		7.6		8.6	7.8	8.0	0.5	
pH (su)	5		7.4		7.8	7.6	7.6	0.2	
J Ammonia Nitrogen (mg/L)	4	<	0.021	<	0.021	0.010	0.010	0.000	
J Nitrate+Nitrite Nitrogen (mg/L)	4		0.100		240.000	$0.320~^{\rm M}$	60.185	119.877	
J Total Kjeldahl Nitrogen (mg/L)	4	<	0.080		0.452	0.098	0.172	0.194	
J Total Nitrogen (mg/L)	4	<	0.140		240.040	0.624	60.357	119.789	
J Dissolved Reactive Phosphorus (mg/L)	4		0.007		0.018	0.014	0.013	0.005	
J Total Phosphorus (mg/L)	4		0.020		0.023	0.020	0.021	0.001	
CBOD-5 (mg/L)	4	<	2.0	<	2.0	1.0	1.0	0.0	
Chlorides (mg/L)	4		1.9		2.6	2.3	2.3	0.3	
Atrazine (µg/L)	2	<	0.02	<	0.02	0.01	0.01	0.00	
Total Metals									
J Aluminum (mg/L)	4	<	0.033		0.318	0.088	0.127	0.132	
Iron (mg/L)	4		0.205		0.531	0.233	0.300	0.155	
J Manganese (mg/L)	4		0.042		0.101	0.058	0.065	0.028	
Dissolved Metals									
Aluminum (mg/L)	4	<	0.033		0.043	0.016	0.018	0.002	
Antimony (µg/L)	4	<	1.9	<	1.9	0.9	0.9	0.0	
Arsenic (µg/L)	4	<	0.4	<	2.1	1.0	0.8	0.4	
Cadmium (mg/L)	4	<	0.000	<	0.014	0.001	0.002	0.003	
J Chromium (mg/L)	4	<	0.009		0.022	0.006	0.010	0.008	
J Copper (mg/L)	4	<	0.013		0.021 ^S	0.008	0.011	0.007	1
J Iron (mg/L)	4	<	0.026		0.098	0.028	0.042	0.038	
Lead (µg/L)	4	<	1.7	<	1.7	8.0	0.8	0.0	
J Manganese (mg/L)	4	<	0.001		0.085	0.028 M	0.035	0.036	
Mercury (µg/L)	4	<	0.1	<	0.1	0.0	0.0	0.0	
Nickel (mg/L)	4	<	0.019	<	0.042	0.010	0.012	0.006	
J Selenium (µg/L)	4	<	1.7		1.7	8.0	1.1	0.4	
Silver (mg/L)	4	<	0.000		0.002	0.000	0.000	0.001	
Thallium (µg/L)	4	<	0.6	<	0.6	0.3	0.3	0.0	
Zinc (mg/L)	4	<	0.012	<	0.030	0.015	0.013	0.004	
Biological									
Chlorophyll a (ug/L)	4		0.27		2.14	0.80	1.00	0.83	
E. coli (col/100mL)	4		205		435	261	290	100	

E=# samples that exceeded criteria; G=value higher than median concentration of all verified ecoregional reference reach data collected in the ecoregion 67f; J=estimate; M=value >90% of all verified ecoregional reference reach data collected in the ecoregion 67f; N=# samples; S=F&W harness-adjusted aquatic life use criteria exceeded.